

~~Boeing Defense and Space Group~~

~~P O Box 3990 Ph. 773-8934 M/S 8.1-55~~

Seattle WA 98124-2499

Renton ENVIRONMENTAL

PAGE (OF)

(SEE BACK FOR INSTRUCTIONS)

Contact	Orgn.	Mail Stop	Phone	Chargeline/Control Number			
Ray Power		63-41	234.7744				
Samplers	Kien Chaput	G-1241	63-41	947-6753			
SAMPLE DESCRIPTION AND LOCATION (INCLUDE PLANT, BLDG. #, SITE SAMPLE #, ETC.)	SAMP DATE	TIME	MATX	COLL TYPE	No. CONT	LAB ID (LAB USE ONLY)	ANALYSIS REQUESTED (Use codes on back to indicate tests)
SP 1-3 Na - 9/8/97	9/8/97	1040	S	G	1	97-B628	VOA, Tot. Met.
SP 1-3 Nb - 9/8/97	↓	1043	S	G	1	97-B629	↓ ↓
Comments/Special Instructions	Relinquished by (SIGNATURE) Kien Chaput	Relinquished by (SIGNATURE)	Relinquished by (SIGNATURE)				
MK outfall Soil	Printed Name Kien Chaput	Printed Name	Printed Name				
60 Cy from SP 1-3	Company Boeing	Company	Company				
North Side	Date 9/8/97 Time 1245	Date	Time				
Report Results as soon as available	Received by (SIGNATURE) Mike DeZure	Received by (SIGNATURE)	Received by (SIGNATURE)				
AS analysis by GFAA	Printed Name MIKE DEZURE	Printed Name	Printed Name				
	Company Ecology	Company	Company				
	Date 9/8/97 Time 1245	Date	Time				

INSTRUCTION FOR COMPLETION OF THE "CHAIN OF CUSTODY & LABORATORY ANALYSIS REQUEST" FORM
(PLEASE PRINT ALL INFORMATION CLEARLY AND USE BALLPOINT PEN.)

PAGE ___ OF ___: Use if additional forms are required (i.e. more than 8 samples are being delivered).

CONTACT: Enter name(s) of person(s) to receive analysis report.

ORGN., MAILSTOP, PHONE: Contact's

CHARGE LINE: 7 digit or 21 digit number of requesting organization.

SAMPLERS: All individuals involved in sampling should print their name(s) in this space.

SAMPLE DESCRIPTION AND LOCATION: Brief description of sample and Plant, Building No. and Column or Door No. where sample was collected. A total of 8 samples can be listed on a single form. Use additional forms if more than 8 samples are being delivered.

SAMP DATE: Date sample taken.

TIME: Time sample taken. Use military time.

Matx: Use the following codes to identify the sample matrix:

S=Solid SI=Sludge So=Solvent A=Aqueous O=Oil

COLL TYPE: Specify GRAB or Composite

No. CONT: Enter the number of sample containers associated with each sample.

LAB ID: This section to be completed by lab personnel.

ANALYSIS REQUESTED: List the constituents (or groups of constituents) for which the sample is to be analyzed. The following codes are the more commonly requested analyses:

MET = Metro Metals (Cr, Cu, Ni, Cd, Pb, Zn, Ag)

TCLP = Metals (Cr, Cd, Pb, Ag, Ba, As, Se, Hg)

TCLP-1 = Metals (Cr, Cd, Pb, Ag, Ba, As, Se)

TCLP-2 = Metals (Cr, Cd, Pb, Ag, Ba)

Miscellaneous Metals (contact Lab personnel)

pH = pH

TS = Total Solids

TDS = Total Dissolved Solids

TSS = Total Suspended Solids

CN = Total Cyanide

FOG = Fats, Oils and Grease (polar and/or non polar)

VOA = Volatile Organic Analysis

TPH-D,G,O = Total Petroleum Hydrocarbons-Diesel,
Gasoline, and/or Heavy Oil

PCB = Polychlorinated Biphenyls

Chlorine in Waste Oil or Oily Wastewater

Flashpoint

Settleable Solids

COMMENTS/SPECIAL INSTRUCTIONS: List in this area additional tests not listed above, special instructions or comments (i.e. meter readings, warnings, etc.).

SIGNATURE BLOCKS: To properly complete the chain of custody portion of this document, each time the sample(s) change possession, the person relinquishing the sample(s) should complete the left most section entitled "RELINQUISHED BY". The person receiving the sample(s) should complete the section directly below entitled "RECEIVED BY". If more than three changes of possession are involved, use additional sheets and attach to the original.

DELIVER SAMPLES TO:	Environmental Analysis Lab Boeing Space Center (Kent, WA) Bldg. 18-62.1 Door 11B1 Phone: 773-8934
--------------------------------	--